			· · ·		ARDEN AVEN PENING - 10		G GARAGE 18-00 AWARD								
CLEARWATER BRIGHT AND BEAUTIFUL · BAY TO BEACH				Innovative Mase Ll 16264 Lake Prior Lake		Matcon Cons 3023 I Tam	truction Services, Inc. N. Florida Ave. pa, FL 33603	Paramount Pa 4613 N. Hespe FL 33	inting & Services, Inc. rides St. Tampa, 614-6911	337 N. Fal Tampa	Corporation kenburg Rd. , FL 33619	715 \ Tarpon Sj	oad & Bridge, LLC Vesley Ave. orings, FL 34689	LLC Blount Rd. Beach, I	rvation Systems, 2001 Pompano FL 33069
	BID ITEMS	QTY	UNIT	UNIT PRICE	AMOUNT	UNIT PRICE	AMOUNT	UNIT PRICE	AMOUNT	UNIT PRICE	AMOUNT	UNIT PRICE		UNIT PRICE	AMOUNT
1	Mobilization	1	LS	\$ 224,000.00	\$ 224,000.00	\$ 53,963.00	\$ 53,963.00	\$ 99,200.00	\$ 99,200.00	\$ 2,500.00	\$ 2,500.00	\$ 150,000.00	\$ 150,000.00	\$ 100,015.00	\$ 100,015.00
2	Concrete repair- Delaminated areas, spalls and exposed metal in vertical	60	CF	¢ 105.00	¢ 04.000.00	¢ 000.00	¢ 50,500,00	¢ 040.75	¢ 40.405.00	¢ 405.00	\$ 25 500 00	¢ 550.00	¢	¢ 407.00	¢ 00.000.00
	and overhead surfaces. Concrete repair- Delaminated areas, spalls and exposed metal in	25	CF	\$ 405.00	\$ 24,300.00	\$ 892.00	\$ 53,520.00	\$ 318.75	\$ 19,125.00	\$ 425.00	\$ 25,500.00	\$ 550.00	33,000.00	\$ 467.00	\$ 28,020.00
3	horizontal surfaces.	25	CF	\$ 365.00	\$ 9,125.00	\$ 323.00	\$ 8,075.00	\$ 272.00	\$ 6,800.00	\$ 420.00	\$ 10,500.00	\$ 650.00	\$ 16,250.00	\$ 296.00	\$ 7,400.00
	Epoxy injection crack repair- Routing and installation of injection ports and	130	LF	φ 000.00	φ 3,123.00	φ 020.00	φ 0,070.00	ψ 212.00	φ 0,000.00	φ 420.00	φ 10,000.00	φ 000.00	φ 10,200.00	φ 200.00	φ 1,400.00
4	cap seal for epoxy injection; installation of epoxy for crack repair in vertical														
	and overhead surfaces.			\$ 45.00	\$ 5,850.00	\$ 51.00	\$ 6,630.00	\$ 27.50	\$ 3,575.00	\$ 55.00	\$ 7,150.00	\$ 105.00	\$ 13,650.00	\$ 31.00	\$ 4,030.00
	Horizontal top slab surface crack and slab on grade crack repair- Routing	1800	LF												
5	and installation of urethane sealant for crack repair in horizontal slab/top														
	surfaces.			\$ 7.00	\$ 12,600.00	\$ 3.50	\$ 6,300.00	\$ 4.50	\$ 8,100.00	\$ 5.50	\$ 9,900.00	\$ 95.00	) \$ 171,000.00	\$ 5.00	\$ 9,000.00
6	Clean and coat rust-stained, surface corroded shear connector bars at	650	EA	¢ 45.00	¢ 00.050.00	¢ 00.00	¢ 40.000.00	¢ 0.05	¢ 0.500.50	¢ 00.50	¢ 00.705.00	¢ 450.00	¢ 07 500 00	<b>* 7</b> 0.00	¢ 40.000.00
	locations throughout the parking garage; refer to detail 2/S3.1. At damaged/broken shear connectors, remove and replace with new	8	EA	\$ 45.00	\$ 29,250.00	\$ 28.00	\$ 18,200.00	\$ 3.85	\$ 2,502.50	\$ 36.50	\$ 23,725.00	\$ 150.00	97,500.00	\$ 72.00	\$ 46,800.00
7	reinforcing steel bar at locations shown on drawings. Refer to detail	0	EA												
	1/S3.1.			\$ 585.00	\$ 4,680.00	\$ 166.00	\$ 1,328.00	\$ 342.50	\$ 2,740.00	\$ 145.00	\$ 1,160.00	\$ 2,200,00	\$ 17,600.00	\$ 678.00	\$ 5,424.00
	Expansion Joint Repair- Remove and replace with new expansion joint in	1	LS	φ 000.00	φ 1,000.00	φ 100.00	φ 1,020.00	φ 012.00	φ 2,110.00	φ 110.00	φ 1,100.00	φ 2,200.00	φ 11,000.00	φ 0/0.00	φ 0,121.00
	the area shown on drawings. Work includes necessary surface preparation		_												
8	as per manufacturer's surface preparation requirements, refer to drawing														
	detail 3/S3.1.			\$ 4,445.00	\$ 4,445.00	\$ 4,663.00	\$ 4,663.00	\$ 2,550.00	\$ 2,550.00	\$ 2,400.00	\$ 2,400.00	\$ 45,000.00	\$ 45,000.00	\$ 6,055.00	\$ 6,055.00
	Heavy-Duty Traffic Grade Waterproofing Membrane - Refer to	1	LS												
	Specification 07185: Installation of waterproof deck membrane at existing														
	coated locations (refer to drawings/plan sheets S2.1 and S2.3). Work														
9	includes necessary surface preparation to accept waterproofing														
	membrane as per manufacturer's surface preparation requirements. Work														
	includes all cant beads at slab transitions and membrane shall extend over			\$ 144.500.00	\$ 144.500.00	\$ 153,793.00	¢ 152 702 00	\$ 280,500.00	¢ 280 500 00	¢ 157 111 00	\$ 157,111.00	¢ 05 000 00	¢ 05.000.00	\$ 261,982.00	\$ 261,982.00
	cant beads. Remove and replace all existing sealants throughout the parking garage,	1	LS	\$ 144,500.00	φ 144,500.00	\$ 153,793.00	\$ 155,795.00	\$ 200,500.00	φ 280,500.00	\$ 157,111.00	\$ 157,111.00	\$ 95,000.00	5 95,000.00	\$ 201,962.00	\$ 201,902.00
	including but not necessarily limited to interface between:	-	23												
	•Control Joints •Topping														
	Slab and Sidewalk •Top														
	concrete														
	<ul> <li>Sidewalks and pre-cast concrete wall panels</li> </ul>														
	Sidewalks and concrete columns     •Concrete														
10	stair system and concrete walls														
	•General - interfaces of concrete elements														
	•Window frame to wall surface at the northeast elevator enclosure														
	•Top of slab surface and vertical surfaces														
	•Exterior wall panel and column														
	•Exterior wall panel and panel														
	Handrail post base perimeters     Installation of any absent horizontal to vertical concrete surface interface														
L	sealants			\$ 185,064.00	\$ 185,064.00	\$ 137,525.00	\$ 137,525.00	\$ 75,500.00	\$ 75,500.00	\$ 93,000.00	\$ 93,000.00	\$ 185,000.00	\$ 185,000.00	\$ 125,664.00	\$ 125,664.00
	Handrail Post Base Repairs - Excavate existing unsound concrete to expose	25	EA												
	corroding metal handrail post base. Clean metal surfaces of corrosion, coat														
11	metal and concrete areas with bonding agent and anti-corrosion coating.														
	Replace excavation with new concrete material. Refer to detail 5/S3.2.			•		<b>•</b> ••••									
	Fill interior of posts with growt at all box doubles return of each factor for the	4	10	\$ 365.00	\$ 9,125.00	\$ 131.00	\$ 3,275.00	\$ 222.80	\$ 5,570.00	\$ 135.00	\$ 3,375.00	\$ 450.00	) \$ 11,250.00	\$ 232.00	\$ 5,800.00
12	Fill interior of posts with grout at all handrail posts; refer to Specification 03720 and drawing detail 6/S3.2.	1	LS	\$ 17,760.00	\$ 17,760.00	\$ 5,166.00	\$ 5,166.00	\$ 2,050.00	\$ 2,050,00	\$ 2,300.00	\$ 2,200,00	\$ 25,000.00	\$ 25,000.00	\$ 1,920.00	\$ 1,920.00
	Handrail Post Base Repairs - When section loss at post base is	10	EA	φ 17,700.00	φ 17,760.00	φ 5,166.00	φ 5,100.00	φ 2,050.00	φ 2,030.00	φ 2,300.00	φ 2,300.00	φ 20,000.00	φ 25,000.00	φ 1,920.00	φ 1,920.00
13	encountered, repair via splicing new pipe segment; refer to detail 4/S3.2.	10	10												
				\$ 680.00	\$ 6,800.00	\$ 274.00	\$ 2,740.00	\$ 375.00	\$ 3,750.00	\$ 225.00	\$ 2,250.00	\$ 1,000.00	\$ 10,000.00	\$ 1,258.00	\$ 12,580.00
-															

	N GARDEN AVENUE PARKING GARAGE 18-0033-EN																								
		BID OPENING - 10/9/19 AWARD - 11/7/19																							
					onry Restoration, Matcon Construction Services, Inc.						Paramount Painting & Services,				Dester			Southern Road & Bridge, LLC			St	tructural Pres	ervati	ion Systems,	
	CLEARWATER	RVVALER			LC						•		orporation burg Rd.			esley Ave.	L	LC		2001					
	BRIGHT AND BEAUTIFUL · BAY TO BEACH			16264 Lakeside Ave SE				3023 N. Florida Ave.				3 N. Hesper	s St. Tampa,		. 33619				Blo	Blount Rd.		Pompano			
				Prior Lake, MN 55372			Tampa, FL 33603			FL 33614-6911			Tam	. 33019	Tarpon Springs, FL 34689				Beach, F		3069				
	BID ITEMS	QTY	UNIT	UNIT PR	RICE	ļ	AMOUNT	U	NIT PRICE		AMOUNT	UN	NIT PRICE		AMOUNT	UNIT PRIC	E	AMOUNT	UNIT PR	RICE	AMOUNT	l	JNIT PRICE		AMOUNT
	Paint Metal Handrail Systems - Remove existing paint coating from all	1	LS			Ī		Ī		Ī				Ī			Ī		Ī			Ī			
	exterior exposed surfaces and any surface corrosion via sandblasting. Paint		_																						
14	metal handrail systems. Refer to specification 09900.																								
	, ,			\$ 33,7	50.00	\$	33,750.00	\$	11,405.00	\$	11,405.00	\$	40,000.00	\$	40,000.00	\$ 13,500.	0 \$	13,500.00	\$ 120,00	0.00	\$ 120,000.00	) \$	28,152.00	\$	28,152.00
	Stucco Repair - Remove and replace existing corner beads at the front	1	LS	· · · · ·			1				,				,				<u> </u>						,
	arched facade framing and exterior columns along the east elevation via																								
	the following:																								
15	•Remove existing stucco finish to expose existing corner beads •Remove																								
	existing metal corner beads and replace with PVC corner beads as shwon																								
	in drawing details 1 and 2/S3.2. •Replace																								
	stucco finish at afftected areas			\$ 16,5	00.00	\$	16,500.00	\$	13,434.00	\$	13,434.00	\$	40,000.00	\$	40,000.00	\$ 5,500.	0 \$	5,500.00	\$ 50,00	0.00	\$ 50,000.00	) \$	23,152.00	\$	23,152.00
	Stucco Repair - Remove and replace any damaged/delaminated/failing	700	SF																						
16	stucco along the east elevation of the parking garage. Refer to																								
	Specification 09221.			\$	45.00	\$	31,500.00	\$	15.00	\$	10,500.00	\$	27.86	\$	19,502.00	\$ 25.	00 \$	17,500.00	\$ 7	8.00	\$ 54,600.00	) \$	27.00	\$	18,900.00
	Remove and replace all stucco finish system along the east elevation,	1	LS																						
17	including all necessary accessories and include use of corrosion resistant																								
	accessories. Refer to Specification 09221.			\$ 92,0	00.00	\$	92,000.00	\$	47,264.00	\$	47,264.00	\$	119,000.00	\$	119,000.00	\$ 133,900.	00 \$	133,900.00	\$ 55,00	0.00	\$ 55,000.00	) \$	3,989.00	\$	3,989.00
	Stucco Repair- Remove and replace any damaged/delaminated/failing	200	SF																						
18	stucco throughout the remainder of the parking garage. Refer to																								
	Specification 09221			\$	45.00	\$	9,000.00	\$	26.00	\$	5,200.00	\$	30.00	\$	6,000.00	\$ 35.	0 \$	7,000.00	\$ 12	0.00	\$ 24,000.00	) \$	34.00	\$	6,800.00
	Paint Exterior Wall Surfaces and Façade – existing painted surfaces at the	1	LS																						
19	front (east) elevation (including front columns, planter walls, office half																								
10	walls and arched façade) and exterior surfaces of stair and elevator																								
	towers. Refer to specification 09900.			\$ 18,6	05.00	\$	18,605.00	\$	8,176.00	\$	8,176.00	\$	30,500.00	\$	30,500.00	\$ 14,267.0	00 \$	14,267.00	\$ 200,00	0.00	\$ 200,000.00	) \$	39,304.00	\$	39,304.00
20	Clean and seal exterior vertical concrete surfaces with a vertical surface	1	LS																						
	water repellent. Refer to specification 07190.			\$ 24,8	40.00	\$	24,840.00	\$	21,674.00	\$	21,674.00	\$	22,650.00	\$	22,650.00	\$ 14,119.0	00 \$	14,119.00	\$ 85,00	0.00	\$ 85,000.00	) \$	26,670.00	\$	26,670.00
	Power wash before construction and after restoration is complete	1	LS																						
21	throughout the parking garage at all horizontal and interior vertical			<b>•</b> • • •		_		_				•			10								10 000	_	10 000 55
- 00	concrete surfaces.				00.00	\$	66,600.00	\$	45,780.00	\$		\$	42,500.00	\$	,	\$ 27,000.			· /		\$ 45,000.00		19,022.00	\$	19,022.00
22	Installation of Concrete overlay/topping material for topping slab	100	SF	\$	75.00	\$	7,500.00	\$	27.00	\$	2,700.00	\$	15.00	\$	1,500.00	\$ 35.	50 \$	3,550.00	\$ 15	0.00	\$ 15,000.00	) \$	28.00	\$	2,800.00
	Exterior Metal Framing Repair- At areas of stucco removal and	200	SF																						
23	replacement, when corroding metal framing is encountered, metal			¢	05.00	¢	7 000 00	<i>•</i>	cc 7-	¢	1750.00	¢	0.75	<b>^</b>	1 050 00	¢		0.400.00	¢ ~		¢ 40.000.00		0.00	¢	4 000 00
<b> </b>	framing is to be cleaned and primed	100	65	\$	35.00	\$	7,000.00	\$	23.75	\$	4,750.00	\$	9.75	\$	1,950.00	\$ 17.0	0 \$	3,400.00	\$8	0.00	\$ 16,000.00	א נ	8.00	\$	1,600.00
24	Exterior Metal Framing Repair- At areas of stucco removal and	100	SF																						
24	replacement, when corroding metal framing is encountered, metal			¢	35.00	\$	3.500.00	¢	9.00	¢	900.00	¢	15.75	¢	1.575.00	¢ _4	0 \$	5.100.00	¢ 05	0.00	\$ 25.000.00		232.00	¢	23.200.00
	framing is to be repaired or replaced SUBTOTAL			Φ	33.00	¢	-,	Ф	9.00	- T		Φ			/	φ 51.		,	φ 25		+		232.00	¢	.,
25						ф Ф	988,294.00			\$	626,961.00	<u> </u>		\$	837,139.50			585,707.00			\$ 1,559,850.00 \$ 311.970.00			¢	808,279.00
20						¢ ,	197,658.80	-		\$	125,392.20			\$	167,427.90			117,141.40			÷ • • • • • • • • •			¢	161,655.80
<b>—</b>	TOTAL CONTRACT					<u>ې</u> 1	,185,952.80	<u> </u>		\$	752,353.20			\$	1,004,567.40		\$	702,848.40			\$ 1,871,820.00	,		\$	969,934.80
	Grand Total					\$ 1.185.952.80				\$ 752.353.20				\$ 1,004,567.40			¢	702 040 40			¢ 107100000			¢	060.024.90
						φÎ	,100,902.80			Ф	152,353.20			Φ	1,004,567.40		\$	702,848.40			\$ 1,871,820.00	,		Ф	969,934.80