Manufacturer

| | | | Manufacturer | | | | | | |
|-------|-------------------------|---|---------------------------------------|-------------|-------------|-------------------|------------|---------------|------------------|
| | | | As Listed on Lake County Contract 22- | | Lake County | | Additional | Clearwater FD | Clearwater Total |
| Qty | Part Number | Description | 730G | List Price | | Lake County Price | Discount? | Price | Price |
| | 55 X8814026305A04 | SCBA | Scott Safety - SCBA, cylinders, masks | \$11,581.73 | 7% | \$10,771.01 | Yes | \$9,020.00 | \$496,100.00 |
| | 55 X8814026301A03 | SCBA with spare harness | Scott Safety - SCBA, cylinders, masks | \$12,870.08 | 7% | \$11,969.17 | Yes | \$10.015.00 | \$550,825.00 |
| | 212 804722-01 | SCBA cylinder | Scott Safety - SCBA, cylinders, masks | \$1,998.51 | 7% | \$1,858.61 | Yes | \$1,560.00 | \$330,720.00 |
| | 126 201650-05 | | Scott Safety - SCBA, cylinders, masks | \$2,647.04 | 7% | \$2,461.75 | Yes | \$2,050.00 | \$258,300.00 |
| | | Regulator upgrade hose | | | | | | | |
| | 185 FP1M40000000000 | Standard SCBA facepiece | Scott Safety - SCBA, cylinders, masks | \$533.02 | 7% | \$495.71 | Yes | \$410.00 | \$75,850.00 |
| | 75 FP1M40002M00010 | SCBA facepiece with communications | Scott Safety - SCBA, cylinders, masks | \$2,165.84 | 7% | \$2,014.23 | Yes | \$1,665.00 | \$124,875.00 |
| | 4 CF5V2DDB | SCBA facepiece battery charger - double | Scott Safety - SCBA, cylinders, masks | \$1,117.62 | 7% | \$1,039.39 | Yes | \$865.00 | \$3,460.00 |
| | 8 CF5V2SS0 | SCBA facepiece battery charger - single | Scott Safety - SCBA, cylinders, masks | \$591.69 | 7% | \$550.27 | Yes | \$460.00 | \$3,680.00 |
| | 26 201506-01 | SCBA facepiece battery | Scott Safety - SCBA, cylinders, masks | \$144.63 | 7% | \$134.51 | Yes | \$110.00 | \$2,860.00 |
| | | | | | 7% | \$388.91 | | | |
| | 8 78-8151-6649-7 | RIT bag mask | Scott Safety - SCBA, cylinders, masks | \$418.18 | | | Yes | \$325.00 | \$2,600.00 |
| | 8 201562-04 | Upgrade kit for RIT Fast Attack | Scott Safety - SCBA, cylinders, masks | \$1,426.69 | 7% | \$1,326.82 | Yes | \$1,105.00 | \$8,840.00 |
| | 8 201673-04 | RIT Fast Attack regulator - C5 | Scott Safety - SCBA, cylinders, masks | \$1,248.50 | 7% | \$1,161.11 | Yes | \$965.00 | \$7,720.00 |
| | 4 201567-01 | RIT Fast Attack cylinder | Scott Safety - SCBA, cylinders, masks | \$1,828.13 | 7% | \$1,700.16 | Yes | \$1,465.00 | \$5,860.00 |
| | 1 200773-01 | SEMS RFID tag writer | Scott Safety - SCBA, cylinders, masks | \$965.98 | 7% | \$898.36 | Yes | \$775.00 | \$775.00 |
| | 20 200774-01 | SEMS RFID tags | Scott Safety - SCBA, cylinders, masks | \$183.50 | 7% | \$170.66 | Yes | \$140.00 | \$2,800.00 |
| | 1 200673-01 | | Scott Safety - SCBA, cylinders, masks | | 7% | \$1,585.11 | Yes | | \$1,320,00 |
| | | SEMS SCBA programmer | | \$1,704.42 | | | | \$1,320.00 | |
| | 4 201088-03 | SEMS antenna | Scott Safety - SCBA, cylinders, masks | \$2,902.65 | 7% | \$2,699.46 | Yes | \$2,250.00 | \$9,000.00 |
| | 2 802837-03 | Special tool kit for service technicians | Scott Safety - SCBA, cylinders, masks | \$1,040.64 | 7% | \$967.80 | Yes | \$837.73 | \$1,675.46 |
| | 30 Smoked Out Shield | Training shield for C5 mask - smoke | BA Shields | \$60.00 | LIST | \$60.00 | No | \$60.00 | \$1,800.00 |
| | 30 Solid Color Shield | Training shield for C5 mask - blackout | BA Shields | \$40.00 | LIST | \$40.00 | No | \$40.00 | \$1,200.00 |
| | 1 9519-4200 | Mask fit test machine | OHD | \$10,900.00 | LIST | \$10,900.00 | No | \$10,900.00 | \$10,900.00 |
| | 1 3010-4023 | Mask fit test machine battery | OHD | \$450.00 | LIST | \$450.00 | No | \$450.00 | \$450.00 |
| | | | | | LIST | | | | |
| | 1 SERPG 9519-4020/5 | 5 year service contract for mask fit test machine | OHD | \$5,795.00 | | \$5,795.00 | No | \$5,795.00 | \$5,795.00 |
| | 2 9513-0550F | Mask fit test adapter | OHD | \$385.00 | LIST | \$385.00 | No | \$385.00 | \$770.00 |
| | 5760 EN91-AA | Batteries - semi annual replacement | Energizer | \$0.85 | LIST | \$0.85 | No | \$0.85 | \$4,896.00 |
| | 70 Hydrostatic testing | 5 year hydrostatic testing - current cylinders | N/A (service item) | \$65.00 | N/A | \$65.00 | No | \$65.00 | \$4,550.00 |
| | 282 Hydrostatic testing | 5 year hydrostatic testing - new cylinders | N/A (service item) | \$65.00 | N/A | \$65.00 | No | \$65.00 | \$18,330.00 |
| | 40 Air Sample | Annual compressor air sample | N/A (service item) | \$175.00 | N/A | \$175.00 | No | \$175.00 | \$7,000.00 |
| | 5 201482-02 | Mask lens | | \$211.91 | LIST | \$211.91 | Yes | \$181.64 | \$908.20 |
| | | | Scott Safety- repair parts | | | | | | |
| | 5 70-0020-1027-3 | Faceseal, size small | Scott Safety- repair parts | \$242.62 | LIST | \$242.62 | Yes | \$207.96 | \$1,039.80 |
| | 5 70-0020-1028-1 | Faceseal, size medium | Scott Safety- repair parts | \$223.32 | LIST | \$223.32 | Yes | \$191.41 | \$957.05 |
| | 5 70-0020-1029-9 | Faceseal, size large | Scott Safety- repair parts | \$244.70 | LIST | \$244.70 | Yes | \$209.74 | \$1,048.70 |
| | 6 78-8151-6291-8 | Headnet, size small | Scott Safety- repair parts | \$261.62 | LIST | \$261.62 | Yes | \$224.24 | \$1,345.44 |
| | 12 78-8151-6292-6 | Headnet, size medium | Scott Safety- repair parts | \$261.62 | LIST | \$261.62 | Yes | \$224.24 | \$2,690.88 |
| | | | | | | | | | |
| | 12 78-8151-6293-4 | Headnet, size large | Scott Safety- repair parts | \$261.62 | LIST | \$261.62 | Yes | \$224.24 | \$2,690.88 |
| | 12 804176-03 | Mask strap, bottom | Scott Safety- repair parts | \$34.18 | LIST | \$34.18 | Yes | \$29.30 | \$351.60 |
| | 12 804178-05 | Mask strap, top | Scott Safety- repair parts | \$35.76 | LIST | \$35.76 | Yes | \$30.66 | \$367.92 |
| | 4 31003922 | Regulator visor | Scott Safety- repair parts | \$33.75 | LIST | \$33.75 | Yes | \$28.93 | \$115.72 |
| | 12 201660-05 | Regulator hose | Scott Safety- repair parts | \$549.81 | LIST | \$549.81 | Yes | \$471.27 | \$5,655.24 |
| | 12 201659-01 | Regulator cover | Scott Safety- repair parts | \$207.51 | LIST | \$207.51 | Yes | \$177.87 | \$2,134.44 |
| | | | | | | | | | |
| | 6 201655-01 | Regulator diaphragm | Scott Safety- repair parts | \$336.45 | LIST | \$336.45 | Yes | \$288.39 | \$1,730.34 |
| | 12 31003910 | Regulator latch | Scott Safety- repair parts | \$8.98 | LIST | \$8.98 | Yes | \$7.70 | \$92.40 |
| | 12 10005229 | Regulator demand valve/latch | Scott Safety- repair parts | \$3.08 | LIST | \$3.08 | Yes | \$2.64 | \$31.68 |
| | 24 31003886 | Regulator purge knob | Scott Safety- repair parts | \$8.69 | LIST | \$8.69 | Yes | \$7.44 | \$178.56 |
| | 6 33481-010 | Regulator purge knob pin | Scott Safety- repair parts | \$3.18 | LIST | \$3.18 | Yes | \$2.73 | \$16.38 |
| | 5 18070-00 | Regulator o-ring | Scott Safety- repair parts | \$7.50 | LIST | \$7.50 | Yes | \$6.43 | \$32.15 |
| | | | | | | | | | |
| | 12 31003890 | Regulator valve stem | Scott Safety- repair parts | \$12.32 | LIST | \$12.32 | Yes | \$10.56 | \$126.72 |
| | 5 10010667 | Regulator o-ring | Scott Safety- repair parts | \$4.69 | LIST | \$4.69 | Yes | \$4.01 | \$20.05 |
| | 5 10010666 | Regulator bearing | Scott Safety- repair parts | \$4.69 | LIST | \$4.69 | Yes | \$4.01 | \$20.05 |
| | 20 10005368 | Regulator gasket | Scott Safety- repair parts | \$19.65 | LIST | \$19.65 | Yes | \$16.84 | \$336.80 |
| | 2 201708-01 | Regulator body assembly | Scott Safety- repair parts | \$504.09 | LIST | \$504.09 | Yes | \$432.07 | \$864.14 |
| | 5 36684-047 | Regulator retaining ring | Scott Safety- repair parts | \$7.50 | LIST | \$7.50 | Yes | \$6.43 | \$32.15 |
| | | | | | | | | | |
| | 5 200923-010 | Pressure reducer o-ring | Scott Safety- repair parts | \$4.58 | LIST | \$4.58 | Yes | \$3.93 | \$19.65 |
| | 5 10007565 | Manifold o-ring | Scott Safety- repair parts | \$4.58 | LIST | \$4.58 | Yes | \$3.93 | \$19.65 |
| | 25 57264-00 | CGA o-ring | Scott Safety- repair parts | \$4.58 | LIST | \$4.58 | Yes | \$3.93 | \$98.25 |
| | 5 10007563 | Pressure reducer o-ring | Scott Safety- repair parts | \$4.58 | LIST | \$4.58 | Yes | \$3.93 | \$19.65 |
| | 4 201365-05 | Low cylinder transfer kit | Scott Safety- repair parts | \$64.47 | LIST | \$64.47 | Yes | \$55.26 | \$221.04 |
| | 5 201609-11 | Shoulder harness assembly | Scott Safety- repair parts | \$1,150.03 | LIST | \$1,150.03 | Yes | \$985.74 | \$4,928.70 |
| | 5 201180-01 | | | \$209.85 | LIST | \$209.85 | Yes | \$179.87 | \$899.35 |
| | | Cylinder retention strap | Scott Safety- repair parts | | | | | | |
| | 20 31003739 | Waist to shoulder strap | Scott Safety- repair parts | \$120.74 | LIST | \$120.74 | Yes | \$103.49 | \$2,069.80 |
| | 10 201608-02 | Female waist strap | Scott Safety- repair parts | \$104.34 | LIST | \$104.34 | Yes | \$89.43 | \$894.30 |
| | 10 201608-01 | Male waist strap | Scott Safety- repair parts | \$102.00 | LIST | \$102.00 | Yes | \$87.43 | \$874.30 |
| | 40 201649-01 | Regulator holder | Scott Safety- repair parts | \$48.66 | LIST | \$48.66 | Yes | \$41.71 | \$1,668.40 |
| | 10 201610-11 | Waist pad | Scott Safety- repair parts | \$831.15 | LIST | \$831.15 | Yes | \$712.41 | \$7,124.10 |
| | 4 201638-01 | Waist pad retention strap | Scott Safety- repair parts | \$58.62 | LIST | \$58.62 | Yes | \$50.24 | \$200.96 |
| | 6 31003732 | Shoulder harness clevis | | \$26.45 | LIST | \$26.45 | Yes | \$22.67 | \$136.02 |
| | | | Scott Safety- repair parts | | | | | | |
| | 6 201611-02 | UEBSS pouch | Scott Safety- repair parts | \$277.85 | LIST | \$277.85 | Yes | \$238.16 | \$1,428.96 |
| | 2 201160-24 | Sensor module | Scott Safety- repair parts | \$2,449.18 | LIST | \$2,449.18 | Yes | \$2,099.30 | \$4,198.60 |
| | 2 201367-11 | SCBA console | Scott Safety- repair parts | \$2,075.74 | LIST | \$2,075.74 | Yes | \$1,779.20 | \$3,558.40 |
| | 2 201163-01 | Battery cap | Scott Safety- repair parts | \$84.60 | LIST | \$84.60 | Yes | \$72.51 | \$145.02 |
| | 240 5082L | Mask bag | Ergodyne | \$39.55 | LIST | \$39.55 | Yes | \$30.00 | \$7,200.00 |
| | 3 Compressor install | Compressor/fill station installation | N/A (service item) | \$3,750.00 | N/A | \$3,750.00 | No | \$3,750.00 | \$11,250.00 |
| | | | | | | | | | |
| | 1 RSC-02036100 | Logistics compressor | RevolveAir | \$58,706.00 | LIST | \$58,706.00 | No | \$58,706.00 | \$58,706.00 |
| | 1 RSF-2322A011 | Logistics fill station | RevolveAir | \$24,393.00 | LIST | \$24,393.00 | No | \$24,393.00 | \$24,393.00 |
| | 1 FH-347-N-50 | Logistics high pressure fill hose - 50' page 10 | SCBAS | \$978.90 | 15% | \$832.07 | Yes | \$753.00 | \$753.00 |
| | 1 EZ-T-BHL-3100 | Logistics high pressure hose reel page 9 | SCBAS | \$1,566.00 | 15% | \$1,331.10 | Yes | \$1,075.65 | \$1,075.65 |
| | 3 AB16-0907 | Logistics SCUBA adapter kit | RevolveAir | \$968.00 | LIST | \$968.00 | No | \$968.00 | \$2,904.00 |
| | 1 4-4-CTX-S | Logistics high pressure hose adapter page 32 | SCBAS | \$6.50 | 15% | \$5.53 | Yes | \$5.00 | \$5.00 |
| | | | SCBAS | | | \$75.14 | | | \$68.00 |
| | 1 YVA3010 | Logistics high pressure hose shut off page 47 | | \$88.40 | 15% | | Yes | \$68.00 | |
| | 1 3/8x1/4-PTR-S | Logistics 3/8 X 1/4 pipe fitting page 33 | SCBAS | \$6.50 | 15% | \$5.53 | Yes | \$5.00 | \$5.00 |
| | 1 RSC-02036100 | Station 47 compressor | RevolveAir | \$58,706.00 | LIST | \$58,706.00 | No | \$58,706.00 | \$58,706.00 |
| | 1 FH-347-N-25 | Station 47 high pressure fill hose - 25' page 10 | SCBAS | \$691.60 | 15% | \$587.86 | Yes | \$532.00 | \$532.00 |
| | 1 6506-4-4 | Station 47 high pressure hose adapter page 32 | SCBAS | \$12.34 | 15% | \$10.49 | Yes | \$9.50 | \$9.50 |
| | 4 8HP586C 6000 | Station 51 storage cylinders | RevolveAir | \$2,589.00 | LIST | \$2,589.00 | No | \$2,589.00 | \$10,356.00 |
| | 1 RSS-06C44100U | | RevolveAir | \$3,510.00 | LIST | \$3,510.00 | No | \$3,510.00 | \$3,510.00 |
| | | Station 51 storage cylider rack | | | | | | | |
| | 1 FH-347-N-25 | Station 51 high pressure fill hose - 25' page 10 | SCBAS | \$691.60 | 15% | \$587.86 | Yes | \$532.00 | \$532.00 |
| | 1 6506-4-4 | Station 51 high pressure hose adapter page 32 | SCBAS | \$12.34 | 15% | \$10.49 | Yes | \$9.50 | \$9.50 |
| | 4 AB16-0916 | CGA to SCUBA adapter | RevolveAir | \$420.00 | LIST | \$420.00 | No | \$420.00 | \$1,680.00 |
| | 2 AB16-0942 | CGA to DIN adapter | RevolveAir | \$506.00 | LIST | \$506.00 | No | \$506.00 | \$1,012.00 |
| SHIPE | | | | | | | | | \$4,500.00 |
| | | | | | | | | TOTAL | \$2,181,450.55 |
| | | | | | | | | , | Q2,101,400.00 |