



Appraisers of Central Florida

PO Box 1599

Belleview, FL 34421

Phone (407) 757-2376

Fax (407) 720-4482

Email AOCF18@outlook.com

APPRAISAL REPORT - FILE # 3788739

COMPANY		VEHICLE OWNER	
Company	City of Clearwater	Name	john stone City of Clearwater
Adjuster	John Stone	Address	1900 grand ave
Claim Number	XXXXX	City	Clearwater
Policy Number		State	FL
Deductible		Zip	33765
Insured Name	CITY OF CLEARWATER	Mobile Phone	7272247564
Date of Loss	April 16, 2025	Home Phone	
Date Contacted	December 9, 2025	Work Number	
Date Inspected	December 10, 2025	Email	johnp.stone@myclearwater.com
Loss Type	Other		
Claim For	Insured		
Assignment Type	Total_loss		
Appraiser	James Hamlin		
VEHICLE INFO		VEHICLE LOCATION	
Year	2020	Location	Repair Shop
Make	Ford	Location Name	CUES TRUCK MANUFACTURER
Model	F-550 Cues Sewer Camera	Address	3019 MERCY DRIVE
VIN	1FDUF5GT8LEC51249	City	Orlando
License Plate	XH7335	State	FL
Color	White	Zip	32808
Mileage	32287	Phone	
Driveable	No	Fax	
TIRE INFORMATION			
	Tire Make	Size	Tread Depth
Left Front			
Right Front			
Left Rear			
Right Rear			
TOWING & SALVAGE		TOTAL LOSS	
Towing Charges	\$ 0.00	Total Loss	Yes
Lien Fee	\$ 0.00	Driveable	No
Admin Fee	\$ 0.00	Total Loss Valuation	Other
Other Charges	\$ 0.00	Request #	
Storage Fee (per day)	\$ 0.00	Valuation Amount / TL %	\$247852.26 / 89.34%
Storage Since		NADA Value / TL %	\$0.00 /
ESTIMATE		SALVAGE BIDS	
Appraisal Amount	\$ 221443.30	Salvage Yard / Contact	Phone
UPD Amount	\$ 0.00	/	Amount
Betterment Amount	\$ 0.00	/	0.00
Deductible	\$	/	0.00
Net Total	\$ 221,443.30		
Agreed Price			

Agreed By		REPAIR SHOP INFO	
Days to Repair		Location Name	
Estimate Released	No	Address	
Supplement #1	0.00	City State Zip	
Supplement #2	0.00	Phone	
Supplement #3	0.00	Fax	
Supplement #4	0.00	Email	
Supplement #5	0.00	TIN	

Appraiser Comments

Sewer camera truck has damage to the body assembly. Appears water has entered the vehicle from the roof and a/c unit assembly. Inside, we found almost the complete interior of the body assembly to have water, mold and mildew damage. Interior ceiling, walls, and flooring damage. Computer equipment, interior seats, desks, TVs,, wiring, storage compartment and cabinets are damaged. The complete body assembly needs to be replaced. Along with most interior contents. Possible additional interior content items will be damaged after a complete tear down. Due to these damages. We feel this vehicle is a total loss.

Completed A.C.V. enclosed. To determined the A.C.V. for this vehicle. The were no dealer comparable available. Used National Deprecation Calculator to determined the value of the vehicle.

Appraisers of Central Florida

PO Box 1599

Belleview, FL 34421

Phone (407) 757-2376

Fax (407) 720-4482

Email AOCF18@outlook.com



Total Loss Summary

File # 3788739**Year:** 2020**Make:** FORD**Model:** F550**VIN #:** 1FDUF5GT8LEC51249**License plate #:** XH7335**Color:** WHITE

Dealer Quotes

#	Name	Contact	Phone	Amount(\$)
1	No Comparable Available			\$0.00
2				\$0.00
3				\$0.00

Salvage Bids

#	Name	Contact	Phone	Amount(\$)
1				\$0.00
2				\$0.00
3				\$0.00

ACV Summary

NADA Value \$247,852.26**Avg Dealer Quotes** \$0.00**Avg Nada & Dealer Quotes** \$247,852.26**Tax Amount (0%)** \$0.00**Adjustments (+)** \$0.00**UPD (-)** \$0.00**Suggested ACV** \$247,852.26

Comments

National Depreciation Calendar 8% 1st year, 7% each additional year.



ACF
 P.O. Box 622492, Orlando, FL 32862
 Office: (407) 757-2376
 aocf18@outlook.com

TOTAL LOSS
 Estimate ID
 25974764
 Original
 Claim Number
 XXXXX

Not An Authorization For repair
 All supplement requests should be sent via email to
 AOCF18@outlook.com, including supporting documents.
 No Supplemental repairs are authorized without approval
 from the Insurance Company.

Owner City of Clearwater 1900 Grand Ave Clearwater, FL 33765 (727) 444-8024 (Work)	Appraiser James Hamlin Classification Field
--	--

City of Clearwater

Loss Type Other	Claim Number XXXXX	Adjuster John Stone johnp.stone@myclearwater.com	Deductible Unknown
Loss Date 04/16/2025	Inspection Site Cues Truck Manufacturer 3019 Mercy Drive Orlando, FL 32808	Inspection Date 12/10/2025	

2020 Ford F-550 Super Duty Chassis Cab XLT 2 Door Regular Cab 193" WB 6.7L 8 Cyl Diesel Injected Turbocharged Base RWD

Exterior Color White	License FL-XH7335	VIN 1FDUF5GT8LEC51249	Condition Good
Drivable Yes	Odometer 32287	Mitchell Service Code 912337	

Primary Point of Impact
 Non-Collision (16)

City of Clearwater | 2020 Ford F-550 Super Duty Chassis Cab XLT

Description 2020 Ford F550 Cues Sewer Camera Truck	Parts Profile ACF Florida	Parts Profile Version 20.0
---	------------------------------	-------------------------------

Line #	Description	LABOR			PART				
		Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
1	Dry Van Chassis								

Line #	Description	LABOR			PART				
		Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
1	900500 Body Assy	Remove / Replace	Mechanical*	25.0*	New		1	\$17,500.00*	Yes
2	900500 EVOLUTION 3.0 INTERIOR	Remove / Replace	Mechanical*	99.5*	New		1	\$57,600.00*	Yes
3	900500 RHINO LINING FLOORING IN VIEWING ROOM AND EQUIPMEN	Remove / Replace	Mechanical*	INC*	New		1	\$2,500.00*	Yes
4	900500 INTERIOR CABINET HARDWARE KIT	Remove / Replace	Mechanical*	INC*	New		1	\$3,004.50*	Yes
5	900500 BLANK PANEL KIT FOR HIGH CUBE/TRAILER TV/LAMP OR T	Remove / Replace	Mechanical*	INC*	New		1	\$1,626.81*	Yes
6	900500 LOW PROFILE, ROOF MOUNTED AIR CONDITIONER	Remove / Replace	Mechanical*	INC*	New		1	\$3,530.96*	Yes
7	900500 WALL MOUNTED ELECTRIC HEATER WITH HOUSING	Remove / Replace	Mechanical*	INC*	New		1	\$2,390.16*	Yes
8	900500 BENCH SEAT WITH CUSHION	Remove / Replace	Mechanical*	INC*	New		1	\$936.92*	Yes
9	900500 CLOSET IN VIEWING ROOM	Remove / Replace	Mechanical*	INC*	New		1	\$1,432.71*	Yes
10	900500 STANDARD INTERIOR LIGHTING FOR HIGH CUBE	Remove / Replace	Mechanical*	INC*	New		1	\$3,409.68*	Yes
11	900500 OPERATORS CHAIR, SWIVEL WITH CASTERS	Remove / Replace	Mechanical*	INC*	New		1	\$791.29*	Yes
12	900500 WINDOW TRIM KIT	Remove / Replace	Mechanical*	INC*	New		1	\$402.45*	Yes
13	900500 MULTI-OUTLET WORKSTATION WITH LIGHTS AND USB PORTS	Remove / Replace	Mechanical*	INC*	New		1	\$5,788.98*	Yes
14	900500 5 DRAWER TOOL CHEST WITH DRAWER LINERS	Remove / Replace	Mechanical*	INC*	New		1	\$987.35*	Yes
15	900500 STORAGE DRAWER UNIT FOR EQUIPMENT ROOM LOWER CABIN	Remove / Replace	Mechanical*	INC*	New		1	\$826.66*	Yes
16	900500 ETHERNET PORT	Remove / Replace	Mechanical*	INC*	New		1	\$273.18*	Yes
17	900500 ENCLOSED LAVATORY	Remove / Replace	Mechanical*	INC*	New		1	\$3,506.77*	Yes
18	900500 22" MONITOR (2 @ \$682.61)	Remove / Replace	Mechanical*	INC*	New		2	\$1,365.22*	Yes
19	900500 32" REAR LED MONITOR IN EQUIPMENT ROOM WITH MOUNT	Remove / Replace	Mechanical*	INC*	New		1	\$914.62*	Yes
20	900500 BASE INTERIOR WIRING	Remove / Replace	Mechanical*	INC*	New		1	\$4,561.09*	Yes
21	900500 PCU ASSEMBLY	Remove / Replace	Mechanical*	INC*	New		1	\$6,400.15*	Yes
22	900500 CCU ASSEMBLY	Remove / Replace	Mechanical*	INC*	New		1	\$3,955.38*	Yes
23	900500 15" LCD MONITOR FOR LAMP WITH WALL MOUNT, SWIVEL B	Remove / Replace	Mechanical*	INC*	New		1	\$587.88*	Yes
24	900500 NUC COMPUTER	Remove / Replace	Mechanical*	INC*	New		1	\$13,455.10*	Yes
25	900500 KEYBOARD AND MOUSE COMBO, WIRED	Remove / Replace	Mechanical*	INC*	New		1	\$803.91*	Yes

Estimate Totals

Taxable	\$221,443.30
Tax	\$0.00
Non-Taxable	\$0.00
Pre-Tax Discount 0.00%	\$0.00
Gross Total	\$221,443.30

Adjustments	Amount
Total Customer Responsibility	\$0.00
Net Estimate Total	\$221,443.30

*****Notice*****

This appraisal is subject to the complete review and approval by the assigning insurance company to assure accuracy, cost effectiveness, and that accepted industry repair standards are met. The insurance company listed has the right to accept or reject any part or all of this appraisal or make any changes they feel necessary.

"Failure to use the insurance proceeds in accordance with the security agreement, if any, could be a violation of  812.014, Florida Statutes. If you have any questions, contact your lending institution." "Any person who knowingly and with intent to injure, defraud, or deceive any insurer files a statement of claim or an application containing any false, incomplete, or misleading information is guilty of a felony of the third degree." "This paragraph shall not apply to reinsurance contracts, reinsurance agreements, or reinsurance claims transactions.

Disclaimer: Any person who knowingly and with intent to injure, defraud, or deceive any insurer files a statement of claim or an application containing any false, incomplete, or misleading information is guilty of a felony of the third degree.

Assignment Info

File # : 3788739
Claim # : XXXXX-G4858
Date : 12/23/2025

Appraisers of Central Florida

PO Box 1599
Bellevue, FL 34421
Phone (407) 757-2376
Fax (407) 720-4482
Email AOCF18@outlook.com



File Name / Description:

DAMAGE_LEFT_WALL_INTERIOR



File Name / Description:

AC_UNIT



File Name / Description:

IMG_6942



File Name / Description:

FRONT

Assignment Info

File # : 3788739
Claim # : XXXXX-G4858
Date : 12/23/2025

Appraisers of Central Florida

PO Box 1599
Bellevue, FL 34421
Phone (407) 757-2376
Fax (407) 720-4482
Email AOCF18@outlook.com



File Name / Description:

IMG_6940



File Name / Description:

UPD_DENT_RIGHT_REAR_ROOF



File Name / Description:

IMG_6938



File Name / Description:

UPD_RIGHT_BACK_DOOR_LOCK_BROKE
N

Assignment Info

File # : 3788739
 Claim # : XXXXX-G4858
 Date : 12/23/2025

Appraisers of Central Florida

PO Box 1599
 Belleview, FL 34421
 Phone (407) 757-2376
 Fax (407) 720-4482
 Email AOCF18@outlook.com



File Name / Description:

REAR



File Name / Description:

LEFT_REAR



File Name / Description:

TAG_BOX



File Name / Description:

VIN_DOOR

J & B Truck Body, Inc.
 SERIAL NO. 134201696840320
 MODEL FRP VAN BODY
 J & B TRUCK BODY
 1476 L & R INDUSTRIAL BLVD. TARPON SPRINGS, FL 34689
 PHONE : 727-943-8911

INCOMPLETE VEHICLE MFD. BY FORD MOTOR COMPANY
 DATE: 01/20
 FRONT GAWR: 3175 KG (7000 LB)
 WITH 225/70R19.5G 128/126N
 19.5X6.0RW
 AT 655 kPa/ 95 PSI COLD
 VIN: 1FDUF5GT8LEC51249
 GVWR: 8845 KG (19,500 LB)
 REAR GAWR: 6671 KG (14706 LB)
 WITH 225/70R19.5G 128/126N
 19.5X6.0RW
 AT 760 kPa/ 110 PSI COLD
 TIRES RIMS DUAL
 RC 24 DSO:
 99S AS 5 8L G AAEE ULN
 MADE IN U.S.A. SUSA-3520472-AA

Assignment Info

File # : 3788739
Claim # : XXXXX-G4858
Date : 12/23/2025

Appraisers of Central Florida

PO Box 1599
Bellevue, FL 34421
Phone (407) 757-2376
Fax (407) 720-4482
Email AOCF18@outlook.com



File Name / Description:

ODOMETER



File Name / Description:

INTERIOR



File Name / Description:

VIN_DASH



File Name / Description:

LEFT_FRONT

Assignment Info

File # : 3788739
Claim # : XXXXX-G4858
Date : 12/23/2025

Appraisers of Central Florida

PO Box 1599
Bellevue, FL 34421
Phone (407) 757-2376
Fax (407) 720-4482
Email AOCF18@outlook.com



File Name / Description:

RIGHT_FRONT



File Name / Description:

LOGO



File Name / Description:

UPD_DENTS_RIGHT_SIDE_AND_SIDE_DOOR



File Name / Description:

RIGHT_REAR

Assignment Info

File # : 3788739
Claim # : XXXXX-G4858
Date : 12/23/2025

Appraisers of Central Florida

PO Box 1599
Bellevue, FL 34421
Phone (407) 757-2376
Fax (407) 720-4482
Email AOCF18@outlook.com



File Name / Description:

DAMAGE_LEFT_WALL_MOLDING_AND_S
TAINED



File Name / Description:

DAMAGE_VENT_BATHROOM_LEAKING



File Name / Description:

DAMAGE_WATER_STAINS_BATHROOM_D
OOR



File Name / Description:

DAMAGE_LEFT_BATHROOM_OUTER_WAL
L_STAINED_AND_MOLDING

Assignment Info

File # : 3788739
Claim # : XXXXX-G4858
Date : 12/23/2025

Appraisers of Central Florida

PO Box 1599
Bellevue, FL 34421
Phone (407) 757-2376
Fax (407) 720-4482
Email AOCF18@outlook.com



File Name / Description:

IMG_6918



File Name / Description:

DAMAGE_AC_UNIT_LEAKING



File Name / Description:

DAMAGE_INTERIOR_RIGHT_SIDE_WALL
L_STAINED_AND_MOLDING



File Name / Description:

DAMAGE_RIGHT_INTERIOR_WALL_AND
_DOOR_STAINED_AND_MOLDING



Assignment Info

File # : 3788739
Claim # : XXXXX-G4858
Date : 12/23/2025

Appraisers of Central Florida

PO Box 1599
Belleview, FL 34421
Phone (407) 757-2376
Fax (407) 720-4482
Email AOCF18@outlook.com



File Name / Description:

BOX_INTERIOR



File Name / Description:

LICENSE